GLOBAL SAFETY FIELD INVESTIGATIONS DCS4049 URGENT - DISTRIBUTE IMMEDIATELY

Date: May 20, 2016

Subject: 15822A - Safety Recall

Seatbelt Lap Anchor Tensioner Cable – Driver's Side Temporary Remedy for Used and Customer Vehicles

Models: 2014-2015 Chevrolet Silverado 1500 Series

2014-2015 GMC Sierra 1500 Series

To: All Chevrolet and GMC Dealers

An interim inspection procedure is now available for used vehicles and customer vehicles. The interim inspection procedure involves an inspection, and if evidence of fatigue, fraying, separation or any other problem exists, a driver seat belt tensioner kit must be installed. This is a temporary repair and these vehicles will require an additional repair when parts for the final remedy are available. This interim inspection procedure should not be used on new, unused and unsold vehicles in dealer inventory with 50 miles (80 km) or more on the odometer or GM Certified Used vehicles in dealer's possession. Please discard all copies of bulletin 15822.

This recall has two different final remedies; one, which is published in this bulletin, for new, unused, and unsold vehicles in dealer inventory with less than 50 miles (80 km) on the odometer, and another, to be published later, for unsold new vehicles with greater than 50 miles (80 km) on the odometer, used vehicles, and customer vehicles.

Details of this recall are shown below.

- New, unused, and unsold vehicles in dealer inventory with less than 50 miles (80 km) on the odometer permanent repair is available (install driver seat belt kit).
- Vehicles in used inventory and customer vehicles an interim inspection procedure is available (inspect, and if necessary, install driver seat belt tensioner kit). This repair will not close this recall. These vehicles will require the permanent repair when it becomes available.
- New, unused, and unsold vehicles in dealer inventory with 50 miles (80 km) or more on the odometer a repair is not yet available. Do not use the interim inspection procedure on these vehicles.
- GM Certified Used vehicles a repair is not yet available. Do not use the interim inspection procedure on these vehicles.

Additional information will be provided as it becomes available.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS